

# KING EDWARDS III MANOR HOUSE

## STABILISATION OF THE RUIN, DURING 2005

The ruins of King Edward III Manor House C14 were unearthed during the demolition of warehouses approximately ten years previous to this project.

Whilst this was totally buried, it was decided at that time that part of the ruin should be left exposed for public viewing.

Years of vandalism lead English Heritage to ensure that the remaining visible ruin would survive for future generations.

The aim of the project was to conserve the remaining exposed fabric, however it was necessary to rebury some of the ruins and prevent further vandalism and destruction.

The work was completed late 2005.



THE CLIENT: LONDON BOROUGH OF SOUTHWARK  
CONTRACTOR: SIMMONDS OF WROTHAM  
GRANT AIDED: ENGLISH HERITAGE LONDON REGION.